



HikCentral V1.3.1 What's New

This document briefly introduces the new functions and features in the **HikCentral 1.3.1** updated from Version 1.3.

The content of this manual is furnished for informational use only and it is subject to change without notice.

1. Added

1.1 VSM Server

- **New models of access control device accessible: DS-5603T-Z, DS-K1T301, and DS-K1T804 series.**

1.2 Web Client

- **New model of fingerprint recorder accessible: DS-K1F310-F**
- **New model of USB webcam: DS-2CS55D7B, which improves the success rate of face recognition, with the captured high definition photos.**
- **Optimized the interactions when recording fingerprints: provides prompts such as "Place your fingerprints." and "Lift your fingerprint".**

1.3 Control Client

- **Added pre-defined window divisions in Monitoring module.**
- **Added duress alarm (access with credentials under duress) when searching access event.**

2 Edited

2.1 VSM Server

- **The trial License and the purchased License can be used in one HikCentral system at the same time.**
- **Optimized the interactions in resource display. It will display the logical resource name when showing the channels of one device.**

2.2 Web Client

- **When editing security control partition, you are required to disarm**

the device unless you just edit the partition name.

- **Access Control:**

- Optimized the compression of the person profiles when importing persons in a batch, which improves the success rate of applying face pictures to the devices.
- Supports applying person list to the access control devices.
- Adding card with effective periods is not allowed if the person is not configured with any cards.
- The maximum length of the person's full name (first name + last name) is 31 characters.

- **Bug fixed:**

- Fixed the bug that when testing people queuing-up alarm, the system might crash.
- Fixed the bug that when adding online security control devices with 256 alarm inputs, which is in the same subnet with the PC running the Web Client or with the VSM server, the page might be frozen for about five minutes.
- Other bugs.

2.3 Control Client

- **Bugs fixed:**

- Fixed the bug that when exporting alarm logs, the alarm category is null.
- Fixed the bug that the color in the heat map generated on the Control Client is lighter than the color in the heat map generated on the device's web page.
- Other bugs.

2.4 Smart Wall

- **Supports displaying the live view of the cascaded decoder's signal source in roaming window**
- **Supports displaying the live view of the cascaded decoder's (DS-69UDI) local signal source on the smart wall.**
- **Bugs fixed.**